



## USB Cable 3.0 A Male / B Male 5 m

**GGM USB3AB5M**



Connect your printer, scanner or peripheral to a computer via USB 3.0 USB 3.0 SuperSpeed 5 Gbit/s cable.

- Sheath type : PVC
- Connector A : USB-A
- Connection type A : Plug
- Insert direction connection 1 : Straight
- Number of connectors A : 1
- Connector B : USB-B
- Connection type B : Plug
- Insert direction connection 2 : Straight
- Number of connectors B : 1
- Length : 5 m